

## Appendix F

### **Intersections with Visibility and Safety Concerns**

The Public Safety Department and the Department of Public Works work together to identify intersections where overgrowth of vegetation can cause visibility and safety concerns. The following list was discussed in an interview with Chief Kevin Mooney.

1. Rt. 117 & Lincoln Road  
(The private property fence on one corner and Drumlin Farm sign on the other corner block sight lines from Lincoln Road going north across Rt. 117.)
2. Rt. 117 & Tower Road
3. Lincoln Road and Codman Road
4. Five Corners, especially from Trapelo and Weston Roads
5. Rt. 2 and Bedford Rd.
6. Rt 2A and Bedford Rd.
7. Crosby's Corner
8. Rt. 126 and Rt. 117
9. Old County and Trapelo Road

Sandwich boards can block visibility at Five Corners, 117 and Lincoln Road, and at Morningside Lane.

Source: Interview with Chief Kevin Mooney, October 2006

8/31/09